




Mac Specs:




Aggregated Device (raising the Hz made the clicking worse):





Ableton Settings:



iConnectMIDI4+ Settings (Port 3 connected to the DAW, Port 1 to iPad Air 2, raising buffer and sync values didn't change anything):

Information	Value
▼ Audio Information	
Number of Audio ports	3
Number of Audio USB Device jacks	3
Number of buffered audio frames	<input type="text" value="2"/>
Sync factor value	<input type="text" value="2"/>
Audio configuration	<input type="text" value="1 - 44100Hz, 4 Channels, 16bit"/>
Clock source	<input type="text" value="4 - Audio Port 3 Clock"/>

Input Channels	Output Channels
▼ iCM4 USB D1	
Channel 1	<input type="text" value="iCM4 USB D3 Ch. 1"/>
Channel 2	<input type="text" value="iCM4 USB D3 Ch. 2"/>
▼ iCM4 USB D2	
Channel 1	<input type="text" value="Nothing"/>
Channel 2	<input type="text" value="Nothing"/>
▼ iCM4 USB D3	
Channel 1	<input type="text" value="iCM4 USB D1 Ch. 1"/>
Channel 2	<input type="text" value="iCM4 USB D1 Ch. 2"/>